

(1) Surface treatment: Service load:

Sendzimir Galvanized 100 Kg per support point

Accessory for anti-rolling continuous concrete beams. Assembled with NOXI profile, FER screw TF12-70, washer A12, Grower washer A12 and nut T12. With this system, assembly regulation is achieved in 2 of the 3 main axes.

Anchor C200




www.noxifer.com



1. Other surface treatment available under request.


Anchor C200

INSTRUCTIONS FOR USE



1.1.- Place the FER screw into profile and turn it 90 degrees.


*The profile can be: NOXI C, R or S; depending on the loads.



2.1.- Assembly of the screw and the anchor through the hole \emptyset 13, leaving the shorter wing of the anchor in contact with the beam.

2.2.- The FER screw must be in contact with the concrete beam to be fixed.

2.3.- Fixing by washer A12, Grower washer AG12 and nut T12.



3.1.- Tighten the nut to finish the assembly. The Grower washer should be left completely flat.

3.2.- Final check and assurance of nut tightening.

In order to continue the assembly sequence all the steps above described must be successfully overcome.



Camí de Barberà, parc. 21 43424 Sarral (Tarragona) España Tel. 977 890 510 info@noxifer.com www.noxifer.com